From: To: <u>Felipe</u>

Marilyn Mosby

Subject: Date: Nice Ct, Kissimmee FL 34747 Monday, December 28, 2020 4:11:22 PM

Attachments: image001.png

Hi Marilyn,

I hope that you are fine!

See below an estimate that I received from the pool company:



Poolheater

This pool heater has a failed condenser fan motor. Cost to replace this fan motor is \$353. Please let me know if you want this replaced and we will schedule to come back and replace this motor

Let me know how do you want deal with it.

Thank you,

Best Regards,

Felipe Jorge Executive Villas Florida www.executivevillasflorida.com

Email: felipe@execvillas.com



DEFENDANT'S EXHIBIT NO. CASE NO. LKG-22-CR-0007	154
(U.S. v. Marilyn J. Mosby) IDENTIFICATION:	
ADMITTED:	